



MISSED APPROACH : Climb on track 036 to 1600(1010) ft ,then turn right continuing climb to 2400(1810) ft and hold.

OCA/H		A	B	C	D
Straight - In approach		Cat I	830(240)		
Circling		1100(510)		1300(710)	