THE CIVIL AVIATION AUTHORITY OF THAILAND

Aeronautical Information Management Department 222 Soi Vibhavadi Rangsit 28, Vibhavadi Rangsit Rd., Chatuchak, Chatuchak, Bangkok 10900 Thailand NON-AIRAC
AIP SUPPLEMENT

A 41/24 25 JUL 2024

RE-DESIGNATION OF RUNWAY 01R/19L AND 01L/19R AT SUVARNABHUMI INTERNATIONAL AIRPORT (VTBS)

1 INTRODUCTION

With effect from 2 October 2024 at 1900UTC to 3 October 2024 at 1000UTC, the purpose of this AIP Supplement is to inform all concerned regarding the re-designation of runway 01R/19L and 01L/19R in relevant to the establishment of the new third runway (runway 02L/20R) since 8 August 2024 at Suvarnabhumi International Airport.

2 RE-DESIGNATION OF RUNWAY 01R/19L AND 01L/19R

From 3 October 2024 at 0000UTC, the two existing runways at Suvarnabhumi International Airport will be re-designated as follows:

- 2.1 The existing runway 01R/19L is re-designated as **RUNWAY 01/19**.
- 2.2 The existing runway 01L/19R is re-designated as RUNWAY 02R/20L.

3 RUNWAY RE-DESIGNATION PROJECT OVERVIEW

To facilitate runway re-designation activities, the following areas will be temporarily closed or available with conditions. For project details, please refer to the table below.

Table: Periods of runway re-designation works

Periods	Date and Time (UTC)	Details
1	2 Oct 2024, 1900 - 2359	Runway 01R/19L will be closed for re-designation.
		Remark: during this period runway 02L/20R is closed.
		(refer to attachment 1)
2	3 Oct 2024, 0000 - 0959	- Runway 02R/20L will be partially closed for completion of final re-designation works and not be available for departing or arriving aircraft.
		- The closed areas will be marked with barricades and closure visual aids.
		(refer to attachment 2)
		- The specific taxi route for departing aircraft are as follows
		Runway 20R: The aircraft will be instructed to taxi via E3, cross runway 20L then W and F1.
		Runway 02L: The aircraft will be instructed to taxi via E17, cross runway 02R then Z, F and F12.
		- The specific taxi route for arriving aircraft are as follows
		Runway 20R: The aircraft will be instructed to taxi via F, Z cross runway 20L, then E17.
		Runway 02L: The aircraft will be instructed to taxi via F, W, cross runway 02R then E3.
3	From 3 Oct 2024, 1000	Runway re-designation complete.
		(refer to attachment 3)

4 OTHERS

If unforeseen events such as adverse weather might delay the re-designation works, pilots will be informed of any schedule changes via NOTAM.

5 CONTACT

For further information contact via the following:


Unit: Aeronautical Information Service Sub-Division of Suvarnabhumi International Airport

Tel: +662 132 6931-4 Mobile: +666 2598 0608


E-mail: ais_vtbs@airportthai.co.th

6 VALIDITY

This AIP Supplement will remain current until 3 October 2024 at 1000UTC. Any changes to this AIP Supplement will be notified by NOTAM.



X Closure marking



Closure marking

×

Closure area

Barricade

X Closure marking